

Letter of Recognition for Initial Findings

The RMG Sustainability Council (RSC) hereby recognizes that:

Space Sweater Ltd (Jogitala) (23383)

Shi-145/1, Jogitola, Joydebpur

Has successfully completed all remediation measures required from the Accord **initial** inspections for structural, electrical, and fire & life safety conducted in Jul 2018.

RSC engineers have physically verified that all initial finding items in the corrective action plan, developed from the initial inspections and approved by the RSC Chief Safety Officer, have been correctly repaired¹.

The initial inspections covered minimum life safety issues in the areas of structural, electrical, and fire & life safety based on an inspection standard developed with the Government of Bangladesh, as well as national and international safety engineers through the facilitation of the ILO.

Factory is still required to complete all the findings, and the factory safety is a continuous process which requires regular monitoring, maintenance, and in-factory safety systems and practices. The RSC will continue to support the factory managers and workers in institutionalising and further advancing such culture of safety and health at the factory.

The RSC extends our congratulations to ***Space Sweater Ltd (Jogitala) (23383)*** for achieving this safety milestone.

Abdul Haque
Managing Director
RMG Sustainability Council (RSC)

Md. Hassan Nawazis
Chief Safety Officer
RMG Sustainability Council (RSC)

Date: 03/10/2024

¹ This letter of recognition verifies that the factory has successfully remediated all items from the limited initial inspection, and that the items in the corrective action plans were in a correct state of repair at the time of the verification inspection. This letter of recognition should not be considered to be a certification or endorsement on the part of the RMG Sustainability Council (RSC). This letter does not address new findings identified during follow-up inspections conducted after the initial inspections.

